Ken Robbins
Highway Administrator

702 K St.
Belleville, KS 66935

Phone: (785) 527-2235
Fax: (785) 527-5335

Weekly Report to the Commissioners

Department Reports on Non-Routine Activities

Roads and Bridges

- The sealing of 10 Road north of Republic on the Jewel County line will be postponed until after harvest.
- Temporary repairs are being made to Lincoln Road, which was damaged when the road was used as part of a large commercial haul route. Crack sealing will be performed on the new overlay that was damaged by commercial hauling on 270 and 280 Roads.

Lincoln Road repairs utilized hot asphalt, chip rock and a plate compactor to the greatest extent possible. We hope this will get us through harvest and into next year before permanent repairs can be made and the road is sealed.

- The Roads and Bridges Department is evaluating Charter Amendment #2002-01 which prohibits commercial traffic on County Roads except those vehicles that have a point of origin or a point of destination within the County, that can be reached by no other route.
  - The concern is commercial traffic at maximum load limits and high enough frequency to damage a road beyond normal wear and tear; (beyond what taxpayers can afford to repair or maintain).
  - Alternate routes are being considered for commercial hauling of over 5,000 tons per week to avoid the damage this road received this year.
- A grant request was resubmitted to KDOT for the resurfacing of 220 Road between US-36 and Munden. That project will cost about 1.4 million and we are seeking funding assistance for ½ of that.

Community Concerns

ID	Description	Notes/Progress/Resolution	Status
Administration			
132	170 Road from intersection to .8 miles south of US 36; road and drainage improvements are needed.	Investigating solutions and impacts on adjacent properties.	Open
45	Norway Lane; drainage improvements are needed.	KDOT is preparing a scope of work to improve KS-148 that passes through the community of Norway. We have requested an update from the Area Engineer with KDOT.	Open
Construction			
136	Queen Road .75 miles east of 30 Road on the north side; the ditch needs cleared of brush and trees for .25 mile to 40 Road.		Open
139	180 Road and Marble Road intersection; a sight obstruction was reported on the NW corner of the intersection.	Investigating	Open
159	230 Road .5 miles south of Queen Road; possible damaged crossroad culvert.	Investigating	Open
164	Birch Road .37 miles west of 100 Road; landowner has requested crossroad culvert be replaced.	Investigating	Open
165	30 Road .25 miles south of Granite Road on the west side; landowner requesting trees and brush be removed from right of way to improve line of sight.	Investigating	Open
167	Timber Road between 140 Road and 160 Road; landowner requesting trees and brush be cleared from right of way.	Completed	Closed
169	Xavier Road .02 miles east of 70 Road crossroad culvert needs replaced and the road lifted.	Investigating	Open
170	60 Road .5 miles south of Timber Road bridge needs replaced going across Beaver Creek.	Severe substructure damage.	Open
171	100 Road and Penn Road landowner requesting trees and brush be cleared from the right of way.	Investigating	Open
172	Lincoln Road .8 miles east of 300 Road on the south side; trees and brush requested to be removed.	Investigating	Open
173	280 Road .5 miles south of Diamond Road on the west side; a request for trees and brush be removed.	Investigating	Open
174	110 Road .01 miles north of Nickel Road; a crossroad culvert is requested.	Clean out existing culvert.	Open
177	310 Road east side of Rock Road; landowner requesting crossroad culvert be extended.	Intersection is too narrow for semi to turn. Investigating	Open
178	290 Road west side of Queen Road; landowner requesting a culvert extension at the intersection.	Intersection is too narrow for semi to turn. Investigating	Open
179	310 Road .25 miles south of Rock Road on the west side; landowner requesting a culvert extension.	Investigating, (Landowner stated that the driveway is close to a gas line)	Open
184	130 Road .25 miles north of Granite Road; water is staying on the road.	Clean ditches re-shape the road to restore the crown.	Open
194	Jade Road and 120 Road; Landowner requesting a crossroad culvert be installed.	24"x40' CMP needed on the west side of the intersection.	Open
195	Fir Road .0-.5 miles East of 280 Road on the south side; Trees need trimmed back from over the road.	Tree Grinder will be used for side trimming to the fence line.	Open
196	Lincoln road .1 west of 130 road on the south side a Culvert needs installed for a field access.	Completed	Closed
198	Shady Road .1 mile east of 90 Road; Landowner requesting crossroad culverts be replaced.	(2) 30"x40' crossroad culverts are silted in and will have to be replaced.	Open

Community Concerns, *continued*

ID	Description	Notes/Progress/Resolution	Status
199	100 Road.5 Miles N of Fir Road trees need Removed on the west side.		Open
200	Pawnee Trail .3 miles south of Granite Road on the west side; Landowner requesting new driveway culvert be installed.	Install a 24"x40' CMP Locate has been made and marked.	Open
201	110 Road .38 Mile South of Valley Road on the West side. Landowner is requesting a driveway culvert.	Install 18" x 30' CMP	Open
202	270 Road .5 miles south of Nickel Road on the west side; Landowner requesting a driveway culvert.	Completed	Closed
203	Marble road .5 miles west of 150 road on the north side; landowner requests a 18" x 30' culvert be installed.	Install 18" x 30' CMP.	Open
204	90 road .75 miles south of Granite Road on the west side; landowner requests a 24" x 10' extension be added to existing culvert.	Install 24" x 10' extension on existing culvert.	Open
205	210 road .5 miles south of US 36 on east side of road. Landowner requesting new driveway.	Completed	Closed
206	140 road .6 miles south of Queen road on the west side landowner requests a new 30' x 40' CMP	Install 30" x 40' CMP.	Open
207	Lincoln Road .68 miles east of 180 Road on the north side; Landowner requesting a new driveway.	Install a 30"x30' CMP	Open
208	Marble road .07 miles East of 20 road District Operator requests crossroad culvert be replaced.	Completed	Closed
209	90 road .35 miles south of Timber road landowner requests a crossroad box culvert be replaced.	Investigating	Open
210	200 road .25 miles south of Hickory road on west side, landowner requests 10' culvert extension or replace.	Investigating	Open
211	Zeal road at intersection of 130 road on west side, a 24'" x 40' crossroad culvert needs to be installed.	Install 24" x 40' CMP	Open
212	Timber road between 190 road and Talmo Lane, District Operator requests trees and brush be removed.	Investigating	Open
52	70 Road between US 36 and Queen Road; drainage improvements are needed on both sides of the road	60% completed.	Open
Maintenance			
146	160 Road .75 miles north of Diamond Road on the west side; ditch needs cleaned.	Landowner requesting the ditch be cleaned for .25 miles to install new fence, also place riprap around the box culvert to prevent scouring.	Open
154	Lincoln Road .4 miles east of 170 Road on the north side; landowner is requesting ditch be cleaned.	(Investigating) Landowner states excess dirt or silt can be wasted in his field if it can be completed before he plants.	Open
160	20 Road .75 miles north of US 36 on the east side of the road; landowner requesting ditch be cleaned out.	Completed	Closed
183	Ash Road .2 miles west of 190 Road on the south side; landowner requesting ditch be cleaned out to stop water from crossing the road.	When the ditch dries use either the scrapper or an excavator to clean the material out and use it to build the road up. May have to install larger diameter culvert at the intersection.	Open
50	30 Road improvements are needed to restore the crown in the roadway between US 36 and Fir Road.	4 miles have been completed.	Open
53	60 Road between Elm and Ash Roads needs the shoulders pulled and fortified with rock and econo-base then finished with gravel.		Open

Upcoming Events

1. Right-of-Way vacations for a portion of Seapo Trail in Section 21 of Grant Township and for the SW corner of Section 35 in Liberty Township (old Marble/US81 intersection ROW) are being prepared for Commission consideration.